

Custom Precisions Track Roller Bearings

RV ROOM SLIDE-OUTS



PROBLEM

A company that supplies recreational vehicle manufacturers with a mechanism used on RV room slide-outs was using a precision track roller bearing as part of the assembly. The bearings, by design, were through-hardened, which was causing the track rollers to crack and fail.

SOLUTION

Kilian™ engineers inspected the bearings and the assembly and determined the root cause of the failure. The Kilian team then created a customized track roller bearing for the slide-out mechanism. The design was tested extensively by Kilian and by the manufacturer.

The modified Kilian bearing design saved significant costs for the manufacturer. The new part was less expensive and also reduced the downtime and warranty issues that were occurring in the field due to the slide-out difficulties.

The RV manufacturer and its dealers were also pleased with the fix as their reputations were on the line because of the frequent slide-out failures. Due to the success of the track roller bearing, the manufacturer has since pursued more business with Kilian.

HIGHLIGHTS

- Custom bearing assembly solution
- Reduced costs and warranty repairs

Regal Rexnord

Contact us: 1-315-432-0700

kilianbearings.com | regalrexnord.com

The proper selection and application of products and components, including assuring that the product is safe for its intended use, are the responsibility of the customer. To view our Application Considerations, please visit <https://www.regalrexnord.com/Application-Considerations>. To view our Standard Terms and Conditions of Sale, please visit <https://www.regalrexnord.com/Terms-and-Conditions-of-Sale>.

"Regal Rexnord" is not indicative of legal entity. Refer to product purchase documentation for the applicable legal entity. Regal Rexnord and Kilian are trademarks of Regal Rexnord Corporation or one of its affiliated companies.

© 2013, 2025 Regal Rexnord Corporation, All Rights Reserved.
MCCSS-P-7267-KM-EN-US 10/25



KILIAN™