Precision Tork

Permanent Magnet Clutches and Brakes	

Precision Tork units provide constant torque independent of slip speed. They offer excellent overload and jam protection for all drivetrain components and also provide soft starts with zero slip when a preset torque is reached. Precision Tork permanent magnet clutches and brakes do not require maintenance and provide extremely long life.

Magnetic Particle Clutches and Brakes



Warner Electric Precision Tork magnetic particle clutches and brakes are unique because of the wide operating torque range available. Torque to current is almost linear and can be controlled very accurately. The unique features of the magnetic particle clutches and brakes make them ideal for tension control, load simulation, cycling/indexing, and soft starts and stops.

Magnetic Capping Headsets

Warner Electric Precision Tork Magnetic Capping Headsets are 100% interchangeable with many major OEM headsets. Warner Electric headsets feature constant Smooth Torque Technology. They are easy to install and maintain with little adjustment required. The Precision Tork headset has a unique visual scale for setting both application torque & the top load spring.

Permanent Magnet Clutches and Brakes					
Features and Benefits	2				
Special Applications	2				
Applications	3				
Specifications	4				
Mounting Arrangements	4				

How to Order......11

Magnetic Particle Clutches and Brakes

Features and Benefits	13
Design and Operation	14
Selection	15
Applications	17
Clutches - Dimensions and Specifications	20
Mounting Bracket	20
Brakes - Dimensions and Specifications	21
Controls	22

Magnetic Capping Headsets

Complete Headset Replacements	23
Features and Benefits	24
Models Available	24
Rebuild Options	25
Chucks	26





Permanent Magnet Clutch and Brakes

Fast, precise torque adjustment!

Precision Tork™ clutches and brakes

Precision Tork units provide constant torque independent of slip speed. They offer excellent overload and jam protection for all drivetrain components and also provide soft starts with zero slip when a preset torque is reached. Precision Tork permanent magnet clutches and brakes do not require maintenance and provide extremely long life.

Features and Benefits

Fast, precise torque adjustment

- Torque is set with a large knurled adjustment ring.
- Infinite adjustability between minimum and maximum settings. This allows units to be fine tuned to your unique requirement.
- Easy to read graduations.

Torque is constant with respect to speed

- By using the Precision Tork unit, you can solve almost any torque control problem.
- Torque is extremely consistent and smooth at low, as well as high speeds.

No external control or power source

- Simple to install
- · Nothing to monitor
- Unaffected by power interruption or power fluctuation
- Safe to use

Dependable performance


- Smallest possible transition from static to dynamic torque. Virtually eliminates the "stick-slip" phenomenon associated with friction devices.
- Long life. The only wearing parts are the ball bearings.
- Extremely accurate. Precision Tork units out perform all other devices at low RPM.

Versatile mounting: Easy to retrofit

- Clutches are available with hollow bores for mounting on motor shafts or jack shafts.
- Bolt circles allow for fixed mounting, adding a pulley, or stub shaft adapters.
- Brakes are available with solid shaft outputs.

Distributor item

- Off the shelf availability.
- Interchangeable with competitors' products.



Specials are our business. . .



Applications

Unwind tension control

Brake mounted on shaft of unwind spool or bobbin.



Information required:

Full roll diameter (in.) = 6 in. Core diameter (in.) = 4 in. Average tension (lbs.) = 4 lbs. Velocity (feet per min.) = 100 fpm

How to size:

Average radius (in.) = $\frac{\text{Full roll dia. (in.)} + \text{Core dia. (in)}}{4}$ = $\frac{6+4}{4}$ = 2.5 in.

Torque (lb.in.) =

Avg. tension (lbs.) x Avg. radius (in.) $= 4 \times 2.5 = 10$ lb.in.

Check tension range:

Max. tension = Torque (lb.in.) x

$$\frac{2}{\text{Core dia. (in.)}} = 10 \text{ x } \frac{2}{4} = 5 \text{ lbs.}$$

Min. tension = Torque (lb.in.) x

$$\frac{2}{\text{Full roll dia. (in.)}} = 10 \times \frac{2}{6} = 3.3 \text{ lbs.}$$


Slip watts =

Max. tension (lbs.) x velocity (fpm)

44.2 = 11.3 watts

Select Model MC4

Cycling



Information required:


Slip RPM = 500 RPM Torque = 8 lb.in. % slip time of total cycle time = 25%

How to size:

*Watts = .0118 x torque (lb.in.) x slip RPM x % slip time = .0118 x 8 x 500 x .25 = 11.8 watts Select MC4 from the specification chart.

*Note: Consult factory if peak slip watts are extremely high or if duration of slip period is in excess of 1 minute.

Nip roll or pulley tension control





Film tensioning
Constant tensioning
supplied by hysteresis unit.

Information required:

Pulley or nip roll diameter = 4 in. Tension = 6 lbs. Velocity = 100 fpm

How to size:


Torque (lb.in.) = Tension (lbs.) $\times \frac{\text{Dia. (in.)}}{2} = 6 \times \frac{4}{2} = 12 \text{ lb.in.}$

Slip watts = $\frac{\text{Tension (lbs.) x velocity (fpm)}}{44.2} = \frac{6 \times 100}{44.2} = 13.5 \text{ watts}$


Select Model MC5

Overload protection/Torque limiting/Soft start

Motor horsepower method



Torque limitingHysteresis clutch provides overload protection.



Material handling
Hysteresis clutch can provide overload

protection and soft start.

Material handling

Information required:

Motor HP = 1/2 HP Motor RPM = 1750 RPM

How to size:

Torque (lb.in.) = $\frac{\text{HP x 63000}}{\text{RPM}}$ = $\frac{1/2 \times 63000}{1750}$ = 18 lb.in.

Select an MC5 from the specification chart.

Standard Clutches and Brakes

Weight

(lbs.)

10.5 oz.

11 oz.

1.5

2.5

3.5

9.5

Bore

Range/Shaft

Dia. (in.) 1/4

1/4

3/8, 1/2

5/16, 3/8

3/8, 1/2, 5/8

3/8, 1/2, 5/8, 3/4, 7/8, 1

3/8

1/2, 5/8 1

1

1

7/8

1

Specifications



Hollow Bore Configurations

-	1	1	
	1		

Model

Size

MC1.5

MC2

MC3

MC4

MC5

MB3

MB4

MB5

MB5.5

MB6

MB6D

Torque

1-13 oz. in.

0.5-22 oz. in.

0.5-6 lb. in.

0.7-10 lb. in.

1-30 lb. in.

0.5-6 lb. in.

0.7-10 lb. in.

1-30 lb. in.

1-50 lb. in.

1-68 lb. in.

6-136 lb. in.

15-300 lb. in.

MC2.5 0.5-5.0 lb. in.

Heat

Dissipation

(watts)

10

10

15

18

22

72

18

22

72

110

150

300

345

Inertia

(lbs. sq.

in.)

0.02

0.02

0.11

0.14

0.32

1.72

0.14

0.33

1.76

2.79

4.33

8.68

66.09

Bending

Moment

(lb. in.)

5

5

10

10

10

25

Max

RPM

3600

3600

1800

1800

1800

1800

1800

1800

1800

1800

1800

1800

1200

2

3.5

10

12.5

12

26

48

Stub Shaft Adapter

MC5.5	1–50 lb. in.	110	2.74	25	1800	12	3/8, 1/2, 5/8, 3/4, 7/8, 1
MC6	1–68 lb. in.	150	4.28	25	1800	12	3/8, 1/2, 5/8, 3/4, 7/8, 1
MC6D	6–136 lb. in.	300	8.52	25	1800	24	1/2, 5/8, 3/4, 7/8, 1
MC9	15–300 lb. in.	345	65.74	50	1200	48	5/8, 3/4, 7/8, 1, 1-1/8, 1-1/4
MB1	0-1.1 oz. in.	3	0.001	1	3600	2.5 oz.	3/16
MB1.5	1–13 oz. in.	10	0.02	5	3600	11 oz.	1/4
MB2	.5-22 oz. in.	10	0.02	5	3600	11.5 oz.	1/4, 3/8
MB2.5	.5–5.0 lb. in.	15	0.11	10	1800	2.5	3/8, 1/2

10

10

25

25

25

25


50



Solid Shaft Configurations


	3		_	MB9

Typical Mounting Arrangements



Brake:

Typical setup for tensioning wire, film and fibers.



Clutch: **Clutch Coupling:**

material handling, soft starts and torque limiting.

Flexible Coupling

Typical setup for torque limiting protection used for labeling, capping and printing applications.

Stainless Steel Clutches and Brakes

Specifications	Model Size	Torque	Heat Dissipation (watts)	Inertia (lbs. sq. in.)	Bending Moment (lb. in.)	Max RPM	Weight (lbs.)	Bore Range/Shaft Dia. (in.)
	MC1.5	1–13 oz. in.	10	0.02	5	3600	10.5 oz.	1/4
Control of the second	MC2	0.5–22 oz. in.	10	0.02	5	3600	11 oz.	1/4
	MC2.5	0.5–5.5 lb. in.	15	0.11	10	1800	1.5	3/8, 1/2
	МС3	0.5–6 lb. in.	18	0.14	10	1800	2.5	5/16, 3/8
1 4	MC4	0.7–10 lb. in.	22	0.32	10	1800	3.5	3/8, 1/2, 5/8
Hollow Bore	MC5	1–30 lb. in.	72	1.72	25	1800	9.5	3/8, 1/2, 5/8, 3/4, 7/8, 1
Configurations	MC5.5	1–50 lb. in.	110	2.74	25	1800	12	3/8, 1/2, 5/8, 3/4, 7/8, 1
	MC6	1–68 lb. in.	150	4.28	25	1800	12	3/8, 1/2, 5/8, 3/4, 7/8, 1
	currently ava	ilable as s	tainless ste	el prod	ucts.			
anger .	MB1	0-1.1 oz. in.	3	0.001	1	3600	2.5 oz.	3/16



Solid Shaft Configurations

		-			-		
MB1	0-1.1 oz. in.	3	0.001	1	3600	2.5 oz.	3/16
MB1.5	1–13 oz. in.	10	0.02	5	3600	11 oz.	1/4
MB2	.5-22 oz. in.	10	0.02	5	3600	11.5 oz.	1/4, 3/8
MB2.5	.5–5.5 lb. in.	15	0.11	10	1800	2.5	3/8, 1/2
МВ3	0.5–6 lb. in.	18	0.14	10	1800	2	3/8
MB4	0.7–10 lb. in.	22	0.33	10	1800	3.5	1/2, 5/8
MB5	1–30 lb. in.	72	1.76	25	1800	10	1
MB5.5	1–50 lb. in.	110	2.79	25	1800	12.5	1
MB6	1–68 lb. in.	150	4.33	25	1800	12	1

www.warnerelectric.com P-1316-WE 6/18


Stainless steel clutches and brakes for harsh environments

Caustic washdown solutions can cause corrosion and eventual failure in food processing applications such as meat and poultry. That's why we have introduced a new line of all stainless steel clutches and brakes. These units, featuring 400 series stainless steel bearings, are robust enough to handle the most hostile washdown environments and tough enough to perform 24/7.











Hollow Bore Configurations





Drawing A

*Set screw adjustment

*Spanner wrench adjustment


Model	Drawing	Α	В	С	D	E	F
MC1.5	А	1.85	1.62	1.38	0.375	0.24	-
MC2	Α	1.85	1.62	1.35	0.375	0.27	-
MC2.5	Α	2.31	2.52	2.23	0.79	0.29	_
MC3	Α	2.74	2.22	1.98	0.590	0.24	-
MC4	Α	3.23	2.27	2.01	0.98	0.26	_
MC5	Α	4.65	3.18	2.64	1.372	0.45	_
MC5.5	Α	5.29	3.21	2.64	1.372	0.57	_
MC6	В	6.05	3.18	2.02	1.372	0.76	0.18
MC6D	В	7.15	5.03	4.06	1.378	0.29	0.29
MC9	В	9.40	4.18	3.49	1.77	0.56	0.13


Bore & Keyseat Sizes

Model	Keyseat	Lockdown Method	G (Bore)	H (Pilot-Both Ends)	l (Both Ends)
MC1.5 MC2	None None	3/32 Roll Pin 3/32 Roll Pin	1/4 1/4	0.877-0.876 x 0.08 dp 0.877-0.876 x 0.08 dp	3) 6-32 x 5/16 dp 1.25 B.C. 3) 6-32 x 5/16 dp 1.25 B.C.
MC2.5	None 1/8 Key	2) Set Screws2) Set Screws	3/8 1/2	1.655-1.653 x 0.10 dp	3) 10-32 x 7/16 dp 1.875 B.C.
МС3	None None	2) Set Screws2) Set Screws	5/16 3/8	1.383/1.381 x .120 dp	3) 10-32 x 7/16 dp 1.875 B.C.
MC4	None 1/8 Key 3/16 Key	2) Set Screws2) Set Screws2) Set Screws	3/8 1/2 5/8	1.854–1.852 x 0.08 dp	3) 10-32 x 7/16 dp 2.375 B.C.
MC5	None 1/8 Key 3/16 Key 3/16 Key 3/16 Key 1/4 Shallow	2) Set Screws	3/8 1/2 5/8 3/4 7/8 1	2.441/2.440 x .10 dp	3) 10-32 x 1/2 dp 3.00 B.C.
MC5.5	None 1/8 Key 3/16 Key 3/16 Key 3/16 Key 1/4 Shallow	2) Set Screws	3/8 1/2 5/8 3/4 7/8	2.441/2.440 x .26 dp	3) 10-32 x 1/2 dp 3.00 B.C. and 3) 5/16–18 x 0.62 dp 3.50 B.C.
MC6	None 1/8 Key 3/16 Key 3/16 Key 3/16 Key 1/4 Shallow	2) Set Screws	3/8 1/2 5/8 3/4 7/8	2.441/2.440	3) 1/4-20 x 5/16 dp 2.875 B.C.
MC6D	3/16 Key 3/16 Key 3/16 Key 1/4 Shallow	2) Set Screws 2) Set Screws 2) Set Screws 2) Set Screws	5/8 3/4 7/8 1	3.250/3.248	3) 5/16-18 x 1/2 dp 4.00 B.C.
MC9	3/16 Key 3/16 Key 3/16 Key 1/4 Key 1/4 Key 1/4 Key	2) Set Screws	5/8 3/4 7/8 1 1-1/8 1-1/4	3.250/3.248	4) 5/16–18 x 1/2 dp 5.875 B.C. and 3) 5/16-18 x 1/2 dp 4.25 B.C.

www.warnerelectric.com P-1316-WE 6/18

Solid Shaft Configurations






*Thumb screw adjustment

*Spanner	wrench	adi	iustment
Spailiei	WIEIICII	au	เนอแบบเ

Model	Drawing	Α	В	С	D (Shaft)	E	F	G	KEY SEAT	H (Pilot-Both Ends)	l (Both Ends)
MB1	С	0.99	1.37	0.86	3/16	0.51	_	0.170 Flat	-	0.300/0.302 x 0.12 dp	3) 4-40 x 1/4 dp 0.610 B.C.
MB1.5	С	1.85	2.36	1.38	1/4	.98	-	0.230 Flat	-	0.876/0.877 x 0.08 dp	3) 6-32 x 5/16 dp 1.250 B.C.
MB2	С	1.85	2.36	1.35	1/4	1.01	_	0.230 Flat	-	0.876/0.877 x 0.08 dp	3) 6-32 x 5/16 dp 1.250 B.C.
IVIDZ	С	1.85	2.36	1.35	3/8	1.01	_	0.355 Flat	-	0.876/0.877 x 0.08 dp	3) 6-32 x 5/16 dp 1.250 B.C.
MB2.5	С	2.31	3.35	2.23	3/8	1.12	-	0.355 Flat	-	1.653/1.655 x 0.10 dp	3) 10-32 x 7/16 dp 1.875 B.C.
IVIDZ.3	С	2.31	3.35	2.23	1/2	1.12	_	0.430/0.414	0.125	1.653/1.655 x 0.10 dp	3) 10-32 x 7/16 dp 1.875 B.C.
MB3	С	2.74	3.02	1.98	3/8	1.04	0.04	0.355 Flat	_	1.383/1.381 x 0.12 dp	3) 10-32 x 7/16 dp 1.875 B.C.
MB4	С	3.23	2.98	2.01	1/2	0.97	0.09	0.430/0.414	0.125	1.852/1.854 x 0.08dp	3) 10-32 x 7/16 dp 2.375 B.C.
WD4	С	3.23	2.98	2.01	5/8	0.97	0.09	0.518/0.502	0.188	1.852/1.854 x 0.08dp	3) 10-32 x 7/16 dp 2.375 B.C.
MB5	С	4.65	4.48	2.64	1	1.75	0.12	0.860/0.844	0.250	2.441/2.440 x 0.100 dp	3) 10-32 x 1/2 dp 3.000 B.C.
MB5.5	С	5.29	4.53	2.65	1	1.88	0.25	0.860/0.844	0.250	2.441/2.440 x 0.26 dp	3)10-32 x 1/2 dp 3.000 B.C. and 3) 5/16-18 x 0.62 dp 3.500 B.C.
MB6	D	6.05	4.48	2.02	1	2.06	0.18	0.860/0.844	0.250	2.441/2.440	3) 1/4-20 x 5/16 dp 2.875 B.C.
MB6D	D	8.55	6.23	4.06	7/8	1.81	0.24	0.771/0.755	0.188	3.250/3,248	3) 5/16-18 x 1/2 dp 4.000 B.C.
MB9	D	9.40	5.39	3.49	1	1.77	0.13	0.860/0.844	0.250	3.250/3.248	4) 5/16-18 x 1/2 dp 5.875 B.C. and 3) 5/16-18 x 1/2 dp 4.250 B.C.



G

Optional Mounting Bracket

Note: Mount bracket to fixed end cap - side opposite knurled adjustment ring.


Model	Fits Size	Α	В	C	D	E	F	G	Н	ı
MPB-2B	MB1.5, 2	0.270	1.750	1.155	0.390	0.280	2.500	0.755	1.500	3.000
MPB-15B	MB2.5/MC2.5, 3, 4	0.270	2.500	1.155	0.390	0.280	3.500	1.130	2.000	4.000
MPB-70B	MB5/	0.270	4.875	1.155	0.390	0.280	6.000	1.630	3.500	6.000
MPB-120B	MB5.5	0.270	4.875	1.155	0.390	0.280	6.000	1.630	3.500	6.250
MPB-240B	MB6	0.270	4.875	1.155	0.390	0.280	6.500	2.445	4.000	7.500

All dimensions are nominal unless otherwise noted. () denotes (mm)

P-1316-WE www.warnerelectric.com 6/18


All Brackets are 12 gauge (.105") Steel

Heat Dissipation Charts




Torque Setting Charts


MB₁




MC2/MB2




MC2.5/MB2.5




MC3/MB3




MC4/MB4




MC5/MB5




MC5.5/MB5.5




MC6/MB6



MC6D/MB6D




MC9/MB9



^{*}Torque values are approximate.

Stub Shaft Adapters





- Utilized when "clutch coupling" configuration is desired.
- Comes complete with attachment hardware and drive key.
- Stub shaft adapters should be used in conjunction with a flexible coupling.
- · Material is Stainless Steel

Adapter Size	Permanent Magnet Model	Α	В	С	D	E
A1-3/16	MB1	0.9	0.88	3/16	0.18	Flat
A2-14	MB1.5/MC1.5/MB2/MC2	1.60	0.78	1/4	0.15	Flat
A2-58	MB1.5/MC1.5/MB2/MC2	1.60	1.15	5/8	0.15	3/16" Key
A3-38	MB3/MC3	2.36	1.19	3/8	0.19	Flat
A4-38	MB4/MC4	2.86	1.19	3/8	0.19	Flat
A5-1	MB5/MC5/MB5.5/MC5.5	3.45	1.72	1	0.27	1/4" Key
A5-12	MB5/MC5/MB5.5/MC5.5	3.45	1.47	1/2	0.27	1/8" Key
A6-34	MB6/MC6	3.40	1.70	3/4	0.35	3/16" Key
A6D-34	MB6D/MC6D/MB9/MC9	4.65	2.50	3/4	0.50	3/16" Key

^{*}If Solid Shaft Series is used with adapter, thumb screw must be removed and replaced with set screws.

How to Order

1. Torque:

Determine the maximum torque that your application requires. See the application example.

2. Energy Dissipation:

Determine the amount of energy or heat that will be generated during operation. Each clutch or brake is rated for a specific amount of energy, given in units of watts, that it can safely dissipate. Energy calculations for common applications are listed in the applications section.

3. Model Selection:

Select the clutch or brake based on torque and energy requirements. See the specifications under "Heat Dissipation and Torque Setting Charts."

4. Select Bore Size:

Select the proper bore size for the application. Although many standard bores are available, consult the factory if your bore requirement is not listed.

5. Example:

Torque Requirement – 9 lb.in. Energy Requirement – 35 watts Bore Requirement – 5/8 inch Select Model MC5-58

I 1 www.warnerelectric.com P-1316-WE 6/18



Magnetic Particle Clutches and Brakes

Accurate torque control with instantaneous engagement!



Warner Electric
Precision Tork
magnetic particle
clutches and brakes are
unique because of the wide operating
torque range available. Torque to
current is almost linear and can
be controlled very accurately. The
unique features of the magnetic
particle clutches and brakes make
them ideal for tension control, load
simulation, cycling/indexing, and soft
starts and stops.

Specials are our business

• Special Shaft Configurations

Customer specified shaft configurations for easy machine mounting and retrofitting.

Special Torque

Maximum torque configurations to meet customer specifications.

• Special Mounting Configurations

Customer specified bolt patterns, special mounting brackets.

Metric units

Features and Benefits

· Torque independent of slip speed

Torque is transmitted through magnetic particle chains which are formed by an electromagnetic field. The torque is independent of slip speed, depending only on circuit current, and is infinitely variable from 0 (disengaged) to rated torque.

• Precise engagement

Precision Tork magnetic particle clutches and brakes engage to transmit torque with speed and precision. Response of the particles to the field is virtually instantaneous, providing perfectly controlled, jerk-free engagement.

• Customer specified engagement

Engagement time may be very gradual or extremely fast. The frequency and torque of the engagement/disengagement sequence is limited only by the capabilities of the control circuitry.

No wearing parts

There are no friction surfaces to grab or wear, and the units are not affected by changes in atmospheric or other environmental conditions.

• Efficient/Compact design

High torque to size ratio and low consumption of electric power.

• Versatile mounting

Convenient bolt circle for easy mounting. Mounting brackets available for all sizes. Brakes are available with solid shafts and through bore. Can be mounted

horizontally or vertically to solve virtually any motion control requirement.


Distributor Item

Off the shelf availability. Interchangeable with industry standard sizes.

13 www.warnerelectric.com P-1316-WE 6/18


Design and Operation

The inside story.



Operating Principles

The magnetic particle unit consists of four main components: 1) housing; 2) shaft/disc; 3) coil and 4) magnetic powder. The coil is assembled inside the housing. The shaft/disc fits inside the housing/coil assembly with an air gap between the two; the air gap is filled with fine magnetic powder.



Engagement


When DC current is applied to the magnetic particle unit, a magnetic flux (chain) is formed, linking the shaft/disc to the housing. As the current is increased the magnetic flux becomes stronger, increasing the torque. The magnetic flux creates extremely smooth torque and virtually no "stick-slip".

Disengagement

When DC current is removed the magnetic powder is free to move within the cavity, allowing the input shaft to rotate freely.

Cycling

By turning the current to the coil on and off a cycling effect is achieved.



Selection

Sizing

To properly size magnetic particle clutches or brakes the thermal energy (slip watts) and torque transmitted must be considered. If thermal energy and torque are known for the application select the unit from the charts to the right.

RPM

RPM must be known when calculating thermal energy (slip watts). For load simulation, torque limiting and similar applications, RPM is known. For web handling, the RPM is calculated as follows:

Slip RPM* =
$$\frac{12 \text{ x Velocity (feet per min.)}}{\pi \text{ x Full Roll Dia.** (in.)}}$$

*In rewind applications the motor RPM should be higher (10%) than the fastest spool RPM.

**In applications with the web running over a pulley or in a nip roll application use the pulley diameter

Thermal Energy (slip watts)

as the roll diameter.

Tension applications are considered continuous slip applications. When a brake or clutch is slipping, heat is generated. Heat is described in terms of "energy rate" and is a function of speed, inertia, and cycle rate. Heat generated is usually described in terms of thermal energy or slip watts. Starting and stopping applications generate heat when the unit slips during the stopping and starting of the load.

• For continuous slip applications, such as tension control in an unwind or rewind application slip watts are calculated using the following formula:

• For cycling applications heat is generated intermittently, and is calculated using the following formula:


Watts = 2.67 x Inertia (lb.in.²)

$$x\left(\frac{RPM^2}{10.000}\right)x F \frac{cycle}{min}$$


Duty Cycle

The average heat input must be below the clutch or brake's heat dissipation rating. If the application generates intermittent heat dissipation, use the average speed for the thermal energy (slip watts) calculations.

Quick Selection Charts



MPB25/MPC25 Heat dissipation curves based on maximum of 20 watts 400 200 5 10 15 20 25 Torque (lb.in.)




Torque


Tension applications calculate torque as a function of roll radius and tension. Soft/controlled stopping applications calculate torque as a function of inertia, speed and desired time to stop the load. Torque limiting applications calculate torque as the allowable drive through torque. Calculate the torque requirement based on the formulas for the different applications:


• To calculate torque for a web handling application, determine the desired tension in the web then calculate the required torque as follows:

MPB15/MPC15



MPB70/MPC70






- *Use full roll diameter. In applications with the web running over a pulley or in a nip roll application use the pulley diameter as the roll diameter.
- To calculate torque for soft/controlled stop or cycling applications first determine the inertia (WR²), and apply it to the formula below:

Torque (lb.in.) =
$$\frac{\text{Inertia (lb.in.}^2) \times \text{RPM}}{3,690 \times \text{time(s)}}$$

Inertia (WR2) =

[(weight of body) x (radius of gyration*)]²

*to calculate for a cylinder about its axis: Solid cylinder = $R^2 = 1/2r^2$ Hollow cylinder = $R^2 = 1/2(r_1^2 + r_2^2)$



Reflected Inertia (rotational)

In mechanical systems it is common for the rotating parts to operate at different speeds. In clutch and brake applications the WR² is calculated for each part operating at different speeds then reduced to and equivalent WR² at the clutch or brake mounting shaft speed. All the rotating parts WR² are added together and treated as a unit.

The formula for determining the equivalent WR² of a rotating part referred to the clutch or brake shaft is as follows:

$$WR_e^2 = WR^2 x \left(\frac{N}{Ncb}\right)^2$$

Where:

 WR^2 = inertia of the rotating part at N (RPM)

 N = speed (RPM) of the rotating part
 N_{Cb} = speed (RPM) of the clutch or brake shaft

Reflected Inertia (linear)

In complex systems involving both linear and rotating motion, the linearly moving parts can be reduced to the clutch or brake speed by the following equation:

$$WR^2e = W x \left(\frac{V}{2\pi N}\right)^2$$

Where:

W = Weight of body

V = Velocity in feet per minute

N = RPM of the clutch or brake shaft

This equation can only be used when the linear speed has a continuous fixed relation to the rotating speed, such as a conveyor driven by a motor.

To determine torque in an overload protection, torque limiting or soft start application use the following equation:

Torque (lb.in.) =
$$\frac{HP \times 63,000}{RPM}$$

Tension Value Chart

Material	tn (lbs.in. of web width)
Aluminum foils	0.5 to 1.5 (1.0 aver.)/mil
Cellophanes	0.5 to 1.0/mil
Acetate	0.5/mil
Mylar (Polyester)	0.25 to 0.30/mil
Polyethylene	0.25 to 0.30/mil
Polypropylene	0.25 to 0.30/mil
Polystyrene	1.0/mil
Saran	0.05 to 0.20
	(0.10 aver.)/mil
Vinyl	0.05 to 0.20
	(0.10 aver.)/mil

Paper and Laminations

20#/R-32.54 gm/m ²	0.50 to 1.0
40#/R-65.08 gm/m ²	1.0 to 2.0
60#/R-97.62 gm/m ²	1.5 to 3.0
80#/R-130.0 gm/m ²	2.0 to 4.0

Paper

15 lbs./ream (3,000 sq. ft.)	0.5
20 lbs./ream	0.75
30 lbs./ream	1.0
40 lbs./ream	1.5
80 lbs./ream	2.5

Laminations

25 lb. paper/.005" PE/.00032" FOIL/.001" PE 3.0 .001" Cello/.0005" PT/.001" Cello 1.5

When these substrates are coated with polyethylene, nylon polypropylene EVA, EAA, and EEA, add the following tension to the values listed above for the substrate only.

Coating Thickness

•	
0.0005" to 0.0001	0.12
0.0011" to 0.002	0.25

Calculating Web Tension

For sizing brakes on applications in which the applied web tension is unknown, use the following information to determine the approximate tension value.

Applied Web Tension (lbs.) = Approx. Material Tension (lb.in.)

x Roll Width (in.)

Example:

The tension for a twelve inch wide roll of 20# paper stock is unknown. What is the prescribed tension?

Material	tn (lbs.in. of web width)
Cellophane	
.00075"	0.5
.001"	0.75
.002"	1.0
Nylon and Cast (non-Oriented)	Propylene
.00075"	0.15
.001"	0.25
.002"	0.5
Paperboard	
8 pt.	3.0
12 pt.	4.0
15 pt.	5.0
20 pt.	7.0
25 pt.	9.0
30 pt.	11.0
Mylar and Orier	ted Propylene
0.0005"	0.25
0.001"	0.5
0.002"	1.0
Material	tn (lbs./strand)

Material	tn (lbs./strand)
Aluminum Wire	
#20 AWG	4.00
#18 AWG	5.50
#16 AWG	9.00
#14 AWG	10.00
#12 AWG	12.00
#10 AWG	15.00
#8 AWG	25.00
Copper Wire	
#20 AWG	8.00
#18 AWG	10.00
#16 AWG	12.00
#14 AWG	15.00
#12 AWG	18.00
#10 AWG	20.00
#8 AWG	25.00

Solution:


The approximate tension value as noted in the chart above for 20# paper stock is 0.75 lb.in.; thus the tension for this application is $(0.75 \text{ lb.in.} \times 12) = 9 \text{ lbs.}$

Applications


Warner Electric Precision Tork magnetic particle clutches and brakes are the ideal solution for controlling and maintaining torque. If the application is tensioning, load simulation, torque limiting, or soft starts and stops the magnetic particle unit is the preferred torque controlling device.

Typical Applications

- Wire Processing (winding, hooking, cutting)
- Paper/Foil/Film Processing
- Labeling Applications
- Textile Processing
- Material Processing
- Load profile simulation on:
 - Exercise Equipment
 - Flight Simulators
 - Healthcare Equipment
- · Life testing on:
 - Motors
 - Gears
 - Pulleys
 - Belts
 - Chains
 - Many other Rotating Devices
- Conveyors
- Bottle Capping



Controlled Acceleration/Deceleration



Controlled soft stop

Particle brakes and the CBC300 control provide soft stopping of large rotating loads. By controlling the input current, the load is decelerated in a controlled manner without torque spikes, shock, or vibration.

Application Example:

Information Required:

RPM: 1,000 Time to Stop: 3 seconds Inertia*: 400 lb.in.²

*If inertia is not known see page 4 to calculate.

How to Size:

Maximum Torque (lb.in.) =

 $= \frac{\text{Inertia (lb.in.}^2) \times \text{RPM}}{3,690 \times \text{time(s)}}$

 $= \frac{400 \times 1,000}{3,690 \times 3}$

= 36 lb-in

Select a brake that exceeds the maximum torque requirements from the Specification Chart – MPB70.

Controlled soft start

Particle clutches and the CBC300 control provide soft controlled acceleration to prevent tipping or shock during start up.

Application Example:

Information Required:
RPM: 500
Time to Start: 4 sec.
Inertia*: 50 lb.in.²

*If inertia is not known see page 4 to calculate

How to Size:

Maximum Torque (lb.in.) =

 $= \frac{Inertia (lb.in.^2) \times RPM}{3,690 \times time(s)}$

 $= \frac{50 \times 500}{3,690 \times 4}$

= 1.7 lb.in.


Select a clutch that exceeds the maximum torque requirements from the Specification Chart – MPC2.

6/18

17 www.warnerelectric.com P-1316-WE

Tensioning

Magnetic Particle clutches and brakes offer smooth controlled torque for tensioning in both the unwind zone and rewind zone. Torque produced from the magnetic particle clutches and brakes is independent of slip speed, offering a distinct advantage over competing technologies. Since torque can be varied infinitely by varying the input current, the magnetic particle clutches and brakes are ideal in an open loop system. To close the loop in the tensioning system, combine the magnetic particle clutch or brake



Unwind stand under load cell control

Particle brakes and load cell controls with precision load cell sensors provide closed loop tension control.

Application Example:

Information Required:

Full Roll Diameter: 20 inches Tension: 5 lbs. 400 fpm Velocity:

How to Size:

of tension.

Maximum Torque (lb.in.) =

Full roll diameter (in.) x tension (lbs.)

$$= \frac{20 \times 5}{2} \\
= \frac{100}{2} \\
= 50 \text{ lb.in.}$$

Slip RPM = Velocity (fpm) x 12 Full roll diameter x π 400 x 12 20 x π = 76 RPM

Thermal Energy (Slip Watts) = .0118 x Torque (lb.in.) x RPM

 $= .0118 \times 50 \times 76$

= 45 Watts

Select a brake that exceeds the maximum torque and thermal energy requirements from Quick Selection Chart - MPB70.

Rewind stand under dancer control

Particle clutches and the MCS-203 control provide accurate closed loop tension control for rewind applications.

Application Example:

Information Required:

Core Diameter: 3 inches Full Roll Diameter: 9 inches Tension: 5 lbs. Velocity: 300 fpm Input RPM: 500 RPM*

Maximum Torque (lb.in.) =

tension (lbs.) x full roll diameter (in.)

$$= \frac{5 \times 9}{2}$$
$$= 23 \text{ lb-in}$$

Core RPM =
$$\frac{12 \text{ x Velocity (fpm)}}{\pi \text{ x (core diameter)}}$$

= $\frac{12 \text{ x } 300}{\pi \text{ x } 1200}$

Full Roll RPM =
$$\frac{12 \text{ x Velocity (fpm)}}{\pi \text{ x Full Roll Dia.}}$$

$$= \frac{12 \times 300}{\pi \times 9}$$

= 127 RPM

Slip RPM = Input RPM - Full Roll RPM

=500 - 127= 372.68

Thermal Energy (slip watts) =

= .0118 x Torque x Slip RPM

 $= .0118 \times 22 \times 373$

= 99 watts

Select a clutch that exceeds the maximum torque and thermal energy requirements from the Quick Selection Chart - MPC120.

*To maximize tension control and minimize heat generated, select a drive system that will result in an actual input speed as close to, but not less than, 30 RPM greater than the core RPM. In this example, 382 + 30 = 412, would be ideal but 500 RPM was more readily available.

Applications

Torque Limiting/ Overload Protection

The magnetic particle clutches and brakes combined with a Warner® CBC control are effective means to providing protection in the case of jam ups. The magnetic particle clutch and the CBC control can provide precise adjustable torque in torque limiting applications.

Application Example

Information Required:
Motor HP: 1 HP
Motor RPM: 700 RPM

How to Size:


Maximum Torque (lb.in.) =

 $= \frac{HP \times 63,000}{RPM}$

= $\frac{1 \times 63,000}{700}$

= 90 lb.in.


Select a clutch that exceeds the maximum torque requirements from the Selection Chart – MPC120.



Load Simulation

By combining the magnetic particle brake with a microprocessor control, virtually any load simulation can be obtained. The control is programmed with the profile or condition that is to be simulated. The control then feeds the profile to the magnetic particle brake in terms of input current. The brake reads the input current and provides load torque to simulate the condition.

If the application requires programming load profiles, adjusting load torque, or simulating friction or drag loads, the magnetic particle clutches and brakes are the ideal solution.




Exercise Equipment

Brake models provide a smooth controllable resistance for exercise machines. When integrated with a microprocessor control, programming load profiles is possible.

www.warnerelectric.com

Dimensions and Specifications

Clutches




Dimensions

Model	A	В	С	D	E	F	G (Output)	H (Input)	ı	J	K5
MPC2-1	2.11	0.750/0.749	3.73	1.85	0.06	1.16	0.88	0.88	0.2498/0.2492	(3) #6-32 x 0.50 on 1.350 BC	Flat
MPC15-1	2.96	1.125/1.124	4.93	2.80	0.07	1.69	1.00	1.00	0.4998/0.4992	(3) #8-32 x 0.50 on 2.000 BC	2 Flats at 90°
MPC15-2	2.96	1.125/1.124	5.08	2.80	0.07	1.69	1.22	0.92	0.3748/0.3742	(3) #8-32 x 0.50 on 2.000 BC	2 Flats at 90°
MPC25-1	2.96	1.125/1.124	4.93	2.80	0.07	1.69	0.995	1.00	0.4998/0.4992	(3) #8-32 x 0.50 on 2.000 BC	2 Flats at 90°
MPC25-2	2.96	1.125/1.124	5.08	2.80	0.07	1.69	1.22	0.92	0.3748/0.3742	(3) #8-32 x 0.50 on 2.000 BC	2 Flats at 90°
MPC70	4.58	1.625/1.624	6.55	3.67	0.10	2.08	1.35	1.35	0.7497/0.7492	(4) #10-32 x 0.63 on 4.228 BC	0.188 Keyway
MPC120	5.25	1.625/1.624	7.02	4.00	0.10	2.40	1.50	1.35	0.7497/0.7492	(4) #1/4-20 x 0.75 on 4.812 BC	0.188 Keyway
MPC240	6.23	2.4415/2.4405	8.35	4.83	.10	2.62	1.66	1.66	.7495/.7485	(4) #1/4-20 X 0.65 on 5.875 BC	0.188 Keyway

Specifications

Model Number	Max. Drag Torque 0 Excit. (lb.in.)	Rated Torque (lb.in.)	Rated Voltage	Resistance (Ohms)	Rated Current (Amps)	Response Zero Force (Millisec)	Response With Force (Millisec)	Inertia of Output Shaft (lb.in.2)	Max. Heat Dissipation (watts)	Max. Speed Recom. (RPM)	Weight
MPC2	0.40	2	24	92	0.261	8	4	0.001	10	1,800	2
IVIFUZ	0.40	2	90	1552	0.058	8	4	0.001	10	1,800	2
MPC15	0.40	15	24	80	0.302	25	9	0.013	20	1,000	5.5
WPG15	0.40	15	90	1501	0.060	25	9	0.013	20	1,000	5.5
MPC25	0.40	25	24	45	0.533	25	9	0.013	20	1,000	5.5
IVIPU23	0.40	25	90	430	0.533	25	9	0.013	20	1000	5.5
MPC70	1.00	70	24	35	0.677	70	17	0.073	100	1,000	16
WPC/U	1.00	70	90	613	0.147	70	17	0.073	100	1,000	16
MPC120	2.00	120	24	33	0.742	90	25	0.370	140	1,000	22
WPG120	2.00	120	90	475	0.190	90	25	0.370	140	1,000	22
MPC240	2.00	240	24	19.5	1.20	150	45	1.33	200	1000	37
WFUZ4U	2.00	240	90	225.5	0.400	150	45	1.33	200	1000	37




Optional Mounting Bracket (for mounting MPB Brakes and MPC Clutches)

Model	Fits Size	A	В	C	D	E	F	G	Н	ı
MPB-2B	2	0.270	1.750	1.155	0.390	0.280	2.500	0.755	1.500	3.000
MPB-15B	15, 25	0.270	2.500	1.155	0.390	0.280	3.500	1.13	2.000	4.000
MPB-70B	70	0.270	4.875	1.155	0.390	0.280	6.000	1.63	3.500	6.000
MPB-120B	120	0.270	4.875	1.155	0.390	0.280	6.000	1.63	3.500	6.250
MPB-240B	240	0.270	4.875	1.155	0.390	0.280	6.500	2.245	4.000	7.500

All dimensions are nominal unless otherwise noted.

Dimensions and Specifications

Brakes



Dimensions

Model	Α	В	C	D	E	F	G	Н	I (Shaft)	J (Bore)	K	L
MPB2-1	2.11	0.750/0.749	2.23	1.15	0.06	0.70	0.87	-	0.2498/0.2492	-	(3) #6-32 x 0.27 on 1.350 BC	1 Flat
MPB15-1	2.96	1.125/1.124	3.05	1.46	0.07	0.85	1.35	-	0.3748/0.3742	-	(3) #8-32 x 0.30 on 2.000 BC	2 Flats at 90°
MPB15-2	2.96	1.125/1.124	2.05	1.46	0.07	0.85	0.34	0.18	-	0.375/0.376	(3) #8-32 x 0.30 on 2.000 BC	0.125 Thru Hole
MPB15-3	2.96	1.125/1.124	2.70	1.46	0.07	0.85	0.99	_	0.4998/0.4992	-	(3) #8-32 x 0.30 on 2.000 BC	2 Flats at 90°
MPB25-1	2.96	1.125/1.124	2.05	1.46	0.07	0.85	1.35	-	0.3748/0.3742	-	(3) #8-32 x 0.30 on 2.000 BC	2 Flats at 90°
MPB25-2	2.96	1.125/1.124	2.05	1.46	0.07	0.85	0.34	0.18	-	0.375/0.376	(3) #8-32 x 0.30 on 2.000 BC	0.125 Thru Hole
MPB25-3	2.96	1.125/1.124	2.7	1.46	0.07	0.85	0.99	-	0.4998/0.4992	-	(3) #8-32 x 0.30 on 2.000 BC	2 Flats at 90°
MPB70-1	4.57	1.625/1.624	2.62	1.76	0.10	0.98	0.50	0.18	-	0.500/0.501	(4) #10-32 x 0.50 on 4.228 BC	0.125 Thru Hole
MPB70-2	4.57	1.625/1.624	3.37	1.76	0.10	0.98	1.25	-	0.7497/0.7492	-	(4) #10-32 x 0.50 on 4.228 BC	0.188 Keyway
MPB70-3	4.57	1.851/1.850	3.00	1.76	0.10	1.01	0.85			0.6258/0.6252	(4) #10-32 x 0.50 on 4.228 BC	0.188 Keyway
MPB120-1	5.25	1.625/1.624	4.02	2.17	0.10	1.18	1.50	0.50	-	0.500/0.501	(4) #1/4-20 x 0.75 on 4.812 BC	0.156 Thru Hole
MPB120-2	5.25	1.625/1.624	4.02	2.17	0.10	1.18	1.50	-	0.7497/0.7492	-	(4) #1/4-20 x 0.75 on 4.812 BC	0.188 Keyway
MPB120-3	5.25	3.186/3.184	3.30	2.17	0.09	0.95	0.85			0.626/0.625	(2) #1/4-20 x 1.07 on 4.850 BC	0.188 Keyway
MPB240-1	6.23	2.442/2.440	4.66	2.65	0.10	1.46	1.65	-	0.7497/0.7492	-	(4) #1/4-20 x 0.65 on 5.875 BC	0.188 Keyway
MPB240-2	6.23	2.442/2.440	3.51	2.65	0.10	1.46	0.50	-		0.875/0.876	(4) #1/4-20 x 0.65 on 5.875 BC	0.188 Keyway
MPB240-3	6.23	2.442/2.440	3.51	2.65	0.10	1.46	0.50	-	-	1.000/1.001	(4) #1/4-20 x 0.65 on 5.875 BC	0.250 Shallow Keyway

Specifications

=											
Model Number	Max. Drag Torque 0 Excit. (lb.in.)	Rated Torque (lb.in.)	Rated Voltage	Resistance (Ohms)	Rated Current (Amps)	Response Zero Force (Millisec)	Response With Force (Millisec)	Inertia of Output Shaft (lb.in.2)	Max. Heat Dissipation (watts)	Max. Speed Recom. (RPM)	Weight
MPB2	0.40	2	24	92	0.261	8	4	0.001	10	1,800	1
	0.40	2	90	1552	0.058	8	4	0.001	10	1,800	1
MPB15	0.40	15	24	80	0.302	25	9	0.013	20	1,000	2.5
	0.40	15	90	1501	0.060	25	9	0.013	20	1,000	2.5
MPB25	0.40	25	24	45	0.533	25	9	0.013	20	1,000	2.5
	0.40	25	90	430	0.060	25	9	0.013	20	1000	2.5
MPB70	1.00	70	24	35	0.677	70	17	0.073	100	1,000	8
	1.00	70	90	613	0.147	70	17	0.073	100	1,000	8
MPB120	2.00	120	24	33	0.742	90	25	0.370	140	1,000	12.5
	2.00	120	90	475	0.190	90	25	0.370	140	1,000	12.5
MPB240	4.00	240	24	19	1.286	150	45	1.311	200	1,000	20.5
	4.00	240	90	246	0.366	150	45	1.311	200	1,000	20.5

Www.warnerelectric.com P-1316-WE 6/18

Adjustable Torque



TCS-200-1 Manual/Analog

The TCS-200-1/-1H single channel controls are selectable voltage or current controlled power supplies designed to power up to a 16-magnet Electro Disc tension brake system, Electromagnetic Particle Brakes, TB Series brakes, or Advanced Technology tension brakes. These controls operate from a switch-selectable power source of 115 or 230 VAC. They can be operated manually from the front panel or remotely via an analog voltage input, a current input, a remote pot, or a roll follower, External inputs are also provided for remote brake Off, Run, and Stop functions, as well as front panel control of these functions.

Features

- Input: 115/230 VAC, 50/60 Hz
- Output: -1, 0-24 VDC adjustable, 4.25
 Amps continuous
 -1H, 0-24 VDC adjustable, 5.8
 Amps continuous
- Front panel torque adjust
- Front panel brake mode stop switch
 Modes: Stop Brake Full On
 Run Normal Operation
 Off Brake Off
- Remote brake mode switch (same functions as mentioned above)
- Remote torque adjust
- Roll follower input
- 0–10 VDC analog voltage input
- 4-20mA analog current input

System Control



CBC200/CBC300

The CBC 200 and CBC 300 are Constant Current controls for 90 volt coil clutches and brakes. Both can control a single clutch or brake, or a clutch and brake or two clutches or two brakes.

Both operate based on 120 volt AC input. The CBC 200s have one output channel adjustable and one fixed. The CBC 300s have both channels adjustable.

The CBC 200 and CBC 300 provide for potentiometer adjustment on the front of the unit as shown.

The CBC 200-1 and CBC 300-1 provides for input from an external 10K ohm, 2 watt potentiometer.

The CBC 200 C1 and CBC 300 C1 are chassis mount versions of the CBC 200-1 and CBC 300-1.

Features

- Input: 115 VAC 50/60 hz
- Output: Pulse width modulated full wave rectified DC. Constant current, switch selectable ranges designed for 90 volt DC clutches and brakes.
- Circuit Protection: Internal short circuit protection on outputs, but no circuit protection for AC ground faults. Customer supplied 1.5 amps 250 VAC Fast Acting type fuse recommended.
- Status Indicators: "POWER" green LED indicating AC power is applied to the control. "SHORT" red LED indicating that a short circuit condition exists on one or both of the outputs.
- Enclosure: NEMA 1 rated.
- External switching: Mechanical or Electromechanical switching.
 Customer supplied 1 amp, 125 v minimum rating

Dancer/Remote Analog Control



MCS-203/MCS-204/ MCS-166

The MCS-203 is a basic dancer control that automatically controls web tension through the use of a dancer roll and sensor. It is single channel, but can operate two 24 VDC tension brakes in parallel when using two MCS-166 power supplies.

The MCS-204 is a basic remote analog control that can also be operated manually via a front panel tension adjustment potentiometer. It is also single channel with the possibility of operating two 24 VDC tension brakes in parallel when using two MCS-166 power supplies.

Features

- Input: 115/230 VAC, 50/60 Hz
- Output: 0-24 VDC at 3 Amps max.

MCS-203 (only)

- Full P-I-D adjustment
- System gain display

MCS-204 (only)

- Front panel torque adjustment
- Remote potentiometer adjustment
- Roll follower input
- Remote voltage or current analog signal following